molex®

ENGINEERING SPECIFICATION

INSTALLATION INSTRUCTION SHEETS

1.0 SCOPE

This specification consists of installation instructions for the Self Contained Power Connector for tap splice.

2.0 PURPOSE

To define material number system for the above instructions.

3.0 REFERENCE MATERIAL NUMBERS

See pages 2-3 for the actual instruction sheets. These pages can be used as originals.

4.0 DEFINITIONS

Not applicable.

5.0 PROCEDURES

Place one (1) instruction sheet in the smallest unit container.

6.0 IMPLEMENTATION

December 6, 2005

TEMPLATE FILENAME: ENGINEERING SPEC[SIZE A](V. 1). DOC						
SD-19402-004		ETHRODAHL	JMACNEIL	JMACNEIL		
DOCUMENT NUMBER:		CREATED / REVISED BY:	CHECKED BY:	APPROVED BY:		
D	DATE: 2009 / 03 / 04	TOKTAL OF EIGE			1010	
	EC No: WNA2009-0564	INSTALLATION INSTRUCTIONS FOR TAP SPLICE			1 of 3	
REVISION:	ECR/ECN INFORMATION:	TITLE: SELF CONTAINED POWER CONNECTOR			SHEET No.	

COC-3 Self Contained Power Connector Installation Instructions For Tap Splice

The 2-circuit-with-ground tap connector is used to tap non-metallic-sheathed cable in the following wire

ranges and types:

Wire			Optional	
Range			Bench	Optional
AWG	Description	Order No.	Arbor Press	Hand Tool
12-14	Self Contained Power Tap Connector - 2 circuit w/ ground for solid wire	19402-1000 (COC-3)	64006-0200	19285-0074





Reference Information

UL File Number: E182087

CSA File Number: LR18689-C53 NEC Article: 550, 551, and 545

HUD Section: 3280.801

Current: 20A Voltage: 300V

Installation Procedure:

- 1. Carefully strip sheath and paper coverings and prepare the wires to the configuration as shown in **Figure 1**. For reference in the absence of a measuring tool, the distance shown in **Figure 1.1** is approximately equal to strip length.
- 2. Hold the clear strain relief cover with bottom facing upward as shown in Figure 2.
- **3.** Lay wire into locator slots, making sure the black wire is placed into locator slots marked BLK shown in **Figure 2.** Use the two wire locators and spreaders to help guide the wire into place. Press the cable sheath into the integral strain relief slot.
- **4.** While holding the strain relief cover, position the housing's hinge posts into the hinge slots and press down until both lock into place as shown in **Figure 2**.
- 5. Close the strain relief cover and housing by hand. Place the connector assembly into Molex tool as shown in **Figure 3**. Squeeze the tool until the connector bottoms out and the locking latches engage on both sides. OR alternately, squeeze the top and bottom closed with tongue and groove pliers as shown in **Figure 3.1**. Pliers must be a minimum of 10" long. Squeeze firmly on both sides, squarely across the connector with the bottom jaw of the pliers butted up against the T-extension in the housing to ensure wires seat completely into slots.
- 6. Inspect the connector to ensure the wires have been properly engaged into the housing assembly contacts. A properly terminated wire is fully seated into its proper slots with no significant bow of the cover. If the wires are not properly seated into the housing assembly contacts, the wires must be re-terminated with a NEW CONNECTOR. Once the cover has been closed the connector cannot be re-used. Failure to comply with this procedure may result in the failure of the connector.











